Kennecott Minerals
A Division of Kennecott Corpora
P.O. Box 11248
Salt Lake City. Utah 84147

Salt Lake City, Utah 84147 (801) 322-8261

Robert A. Malone Director, Environmental Affairs



orig report to

DIVISION OF OIL, GAS & MINING

Kennecott

Bound File on Shelf 01/035/002

February 12, 1986

Dr. Diamne R. Nielson, Ph.D. Division Director
Oil Gas and Mining Division
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, Utah 84180-1203

Dear Dr. Nielson:

Enclosed, for your information and review, please find a copy of Kennecott's Preliminary and Interim Surface Water Report, "Bingham Canyon Hydrologic/Geotechnical Study, Phase II Project Report" by Morrison-Knudsen Company (November, 1985).

This hydrologic study was initiated by Kennecott in 1984, and this interim study report provides an evaluation of various control options which could be used in developing a best management plan, with various water control options, for managing leach and storm water in the Bingham Canyon watershed.

Should you have any questions or wish to discuss this report, please contact me at 322-8261.

Sincerely,

R. A. Malone

/mf Enclosure

cc: S. D. Taylor, w/o enc.

FILE COPY